



ADMINISTRATIVE RULES OF MONTANA



17.53.1003 HAZARDOUS WASTES OR WASTES WHICH MAY NOT BE BURNED IN A BOILER OR INDUSTRIAL FURNACE

- (1) The following hazardous wastes or wastes derived from any of the following wastes may not be burned in a boiler or industrial furnace: Materials identified with EPA hazardous waste numbers D017, D037, D041, D042, F020, F021, F022, F023, F026, F027, F028, F032, and K001 (containing pentachlorophenol).

Authorizing statute(s): 75-10-405, MCA

Implementing statute(s): 75-10-405, MCA

History: NEW, 2001 MAR p. 169, Eff. 1/26/01.